

To: Wilson, Jennifer[wilson.jenniferA@epa.gov]
From: Bill Pringle
Sent: Thur 5/29/2014 2:04:50 AM
Subject: Pictures

[ZTE Majesty 029.jpg](#)

[ZTE Majesty 030.jpg](#)

[IMG_20140506_105352_435.jpg](#)

[IMG_20140502_190056_325.jpg](#)

[IMG_20140502_190102_445.jpg](#)

1. Picture taken at 6943 Middle rd of snow in north side of yard. Confirmed by WEPCO 30% coal particles
2. Picture taken at 6943 Middle rd of snow in west side of yard. Confirmed by WEPCO 30% coal particles.
3. Window on north west side of my house 6943 Middle rd. Dust was tested and found to have coal present by Environmental Initiatives.
4. Window on north central side of house 6943 Middle rd. Dust was tested and found to have coal present by Environmental Initiatives.
5. Another window in different bedroom. North side of house . Coal present.
6. Another window facing west. Coal present.

We have a total of three windows and one door facing west (towards railroad tracks)
We have a total of three windows facing north (towards coal pile at plant) all have coal present.